




| Pos | Part Number | Description                    | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 1   | 46181367S1  | Shockhousing M53x1 cpl.        |                 | 1.00     |
| 2   | 36120151S   | PLUG SCREW M5X6 CPL.           |                 | 1.00     |
| 3   | 46810893    | O-ring 5,28x1,78 NBR70 black   |                 | 1.00     |
| 4   | 50180095    | HS cylinder-head screw R1/8 I8 |                 | 1.00     |
| 5   | 14460161    | Silentblock 10,05x25x32        |                 | 1.00     |
| 6   | 46811208    | Rubber cap do not open 22x5,5  |                 | 1.00     |
| 7   | 52000219    | Sticker Set XPLOR 90x40        |                 | 1.00     |
| 8   | 46180533S4  | Compression cpl. Silber        |                 | 1.00     |
| 9   | 46180811    | O-ring 22x2 Viton70            |                 | 1.00     |
| 10  | 91010339    | Mainspring (59/61) 72-225 damp |                 | 1.00     |
| 10  | 91010367    | Mainspring (59/61) 81-225 damp |                 | 0.00     |

|    |            |                                |  |      |
|----|------------|--------------------------------|--|------|
| 10 | 91010337   | Mainspring (59/61) 66-225 damp |  | 0.00 |
| 11 | 46181382S  | Plastic Spring Retainer D46 cp |  | 1.00 |
| 12 | RP10022    | Repair kit spring retainer     |  | 0.00 |
| 13 | 50181080   | Rubber pad 17x50x54            |  | 1.00 |
| 14 | 46180692S1 | shock bottom part cpl.         |  | 1.00 |
| 15 | R15006     | REPAIR KIT BEARINGS 07         |  | 0.00 |
| 16 | 46180522S1 | TAP ADJ. REBOUND               |  | 1.00 |
| 17 | 46810010   | Round-wire snap ring 49x1,5    |  | 1.00 |
| 98 | 50180751S1 | SHOCK ABSORBER FLUID 5 LT      |  | 0.00 |
| 99 | RP10013    | Repair kit ADV. R              |  | 0.00 |