



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|--------------------------------|-----------------|----------|
| 1 | 46181367S1 | Shockhousing M53x1 cpl. | | 1.00 |
| 2 | 36120151S | PLUG SCREW M5X6 CPL. | | 1.00 |
| 3 | 46810893 | O-ring 5,28x1,78 NBR70 black | | 1.00 |
| 4 | 50180095 | HS cylinder-head screw R1/8 l8 | | 1.00 |
| 5 | 14460161 | Silentblock 10,05x25x32 | | 1.00 |
| 6 | 46811208 | Rubber cap do not open 22x5,5 | | 1.00 |
| 7 | 52000219 | Sticker Set XPLOR 90x40 | | 1.00 |
| 8 | 46180533S4 | Compression cpl. Silber | | 1.00 |
| 9 | 46180811 | O-ring 22x2 Viton70 | | 1.00 |
| 10 | 91010339 | Mainspring (59/61) 72-225 damp | | 1.00 |
| 10 | 91010367 | Mainspring (59/61) 81-225 damp | | 0.00 |

| | | | | |
|----|------------|--------------------------------|--|------|
| 10 | 91010337 | Mainspring (59/61) 66-225 damp | | 0.00 |
| 11 | 46181382S | Plastic Spring Retainer D46 cp | | 1.00 |
| 12 | RP10022 | Repair kit spring retainer | | 0.00 |
| 13 | 50181080 | Rubber pad 17x50x54 | | 1.00 |
| 14 | 46180692S1 | shock bottom part cpl. | | 1.00 |
| 15 | R15006 | REPAIR KIT BEARINGS 07 | | 0.00 |
| 16 | 46180522S1 | TAP ADJ. REBOUND | | 1.00 |
| 17 | 46810010 | Round-wire snap ring 49x1,5 | | 1.00 |
| 98 | 50180751S1 | SHOCK ABSORBER FLUID 5 LT | | 0.00 |
| 99 | RP10013 | Repair kit ADV. R | | 0.00 |