



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-----------------|--------------------------------|-----------------|----------|
| 1 | S455000003S0100 | Monoshock case M51x1 h19 with | | 1.00 |
| 2 | S012900000S0500 | Compression cpl. | | 0.00 |
| 3 | 14460042 | HS cylinder-head screw M5x20 D | | 1.00 |
| 4 | 50180095 | HS cylinder-head screw R1/8 I8 | | 1.00 |
| 5 | 50180217 | O-ring 27x1,5 Viton70 green IS | | 1.00 |
| 6 | 36120151S1 | screw fill M5x6 cpl. | | 1.00 |
| 7 | 52000312 | Sticker XACT LDS 80x29 | | 1.00 |
| 8 | S938100001S0000 | SPRING SUPPORT | | 1.00 |
| 9 | 91210130 | mainspring (62/65) 36-240 muff | | 0.00 |
| 9 | 91210131 | mainspring (62/65) 39-240 muff | | 0.00 |
| 9 | 91210132 | Main spring (62/65) 42-240,muf | | 0.00 |

| | | | |
|----|-----------------|--------------------------------|------|
| 9 | 91210133 | Main spring (62/65) 45-240,muf | 0.00 |
| 9 | 91210134 | Main spring (62/65) 48-240,muf | 0.00 |
| 9 | 91210135 | mainspring (62/65) 51-245 muff | 0.00 |
| 9 | 91210136 | Mainspring (62) 54-250.0 shock | 0.00 |
| 10 | S828800000S01BQ | Spring seat 26,5x76,5x22,3 cpl | 1.00 |
| 11 | S208600003000FB | O-ring 5,28x1,78 HNBR70 red | 1.00 |
| 12 | 50181207 | Locking nut M12x1 h9 WAF19 | 1.00 |
| 13 | 50181344 | Rebound disc 12x34x3,5 h0 | 1.00 |
| 14 | S625000000S0000 | Piston 12x49,4x18 cpl | 1.00 |
| 15 | 50181091 | Rebound disc 12x43x12,5 h8 | 1.00 |
| 16 | 50180603S7 | Dichtungsträger 50x28 cpl. | 1.00 |
| 17 | 50180126 | Round-wire snap ring 53x1,75 | 1.00 |
| 18 | 50181349 | Cap 50,12x16 h6 | 1.00 |
| 19 | 50181100 | Rubber pad 18x58x46 black | 1.00 |
| 20 | S421800010S0100 | Mounting fork with piston rod | 1.00 |
| 21 | RP10044T | Repair kit adjuster DCC 2023 | 0.00 |
| 22 | 46811205 | Bush M10x12/15/13x9,5 | 1.00 |
| 23 | S918100006S0000 | adjuster rebound red cpl. | 1.00 |
| 24 | R15006 | REPAIR KIT BEARINGS 07 | 0.00 |
| 25 | 50180218 | O-ring 25x1,5 Viton70 | 1.00 |
| 98 | 50180751S1 | SHOCK ABSORBER FLUID 5 LT | 0.00 |
| 99 | RP10043T | shock absorber rebuild kit | 0.00 |