




Pos	Part Number	Description	Additional Text	Quantity
1	50180944S1	MONOSHOCK UPPER PART CPL.		1.00
2	50180213S17	DDC compr.damp. Con SX 13 USA		1.00
3	50180218	O-ring 25x1,5 Viton70		1.00
4	R12012	Ball joint bearing kit top 12m		1.00
5	46180010	Distance bush 10x15/18/24,5x10		2.00
6	52000087	Sticker WP warning 47x63		1.00
7	50180095	HS cylinder-head screw R1/8 I8		1.00
8	46810893	O-ring 5,28x1,78 NBR70 black		1.00
9	36120151	HS lock screw M5x6		1.00
10	46811208	Rubber cap do not open 22x5,5		1.00
11	50180937	Clamp d64		1.00
12	14460042	HS cylinder-head screw M5x20 D		1.00
13	50180938	Spring retainer M56x2x63,8x33		1.00
14	50180965	Intermediate washer spring 64,	MX	1.00
15	91210100S	SPRING 260 45 N/MM		0.00
15	91210101S	SPRING 260 48 N/MM		0.00

15	91210102S	SPRING 260 51 N/MM		0.00
15	91210105S	SPRING 260 60 N/MM		0.00
15	91210104S	SPRING 260 57 N/MM		0.00
15	91210103S	SPRING 260 54 N/MM		0.00
15	91210124S	SPRING 260 42 N/MM		0.00
15	91210123S	SPRING 260 39 N/MM		0.00
15	91210128S	Spring 255 36 N/MM		0.00
15	91210126	Mainspring (62/65) 33-250 damp		0.00
15	91210129	Mainspring (62/65) 30-250 damp		0.00
16	50180793	Intermediate washer spring 61,		1.00
17	50180824	Spring retainer 61,5x79,1x7		1.00
18	50180273	Round-wire snap ring 58,5x2		1.00
19	50180141	Piston rod nut 16x1		1.00
20	50180836	Rebound disc 16x34x2 h0		1.00
21	50180786S	piston 16,05x50x20 cmpl.		1.00
22	50180961	Rebound disc 16x43x15 h12		1.00
23	50180603SA	Sealholder 50x28 cpl.		1.00
24	50180780	Spring (3,2) 30-30		1.00
25	50180798	Rubber pad rebound 28,8x48x8		1.00
26	50180800	Spring retainer 18,6x43,7x2 re		1.00
27	50180605S	Seal ring cpl. 18x30x5		1.00
28	50180604	Shim 29.75x19x0.4		1.00
29	46180119	Guide bushing 18x20x12	optional part	1.00
30	50180103	O-ring 41x5 NBR70		1.00
31	50180606	Dirt scarper NOK 18mm black		1.00
32	50180126	Round-wire snap ring 53x1,75		1.00
33	50180626	Cover 50x6 h16		1.00
34	50180775	Rubber pad 17x59x64		1.00
35	46811205	Bush M10x12/15/13x9,5		1.00
36	50180773SA1	MONOSHOCK BOTTOM PART CPL.		1.00
37	50180751S1	SHOCK ABSORBER FLUID 5 LT		1.00
99	R12018	REPAIR-KIT		0.00