



|    |             |                                |  |      |
|----|-------------|--------------------------------|--|------|
| 11 | 36120015    | Lock nut shock M44x1,5         |  | 1.00 |
| 12 | 36120418    | Adjustment nut shock M44x1,5   |  | 1.00 |
| 13 | 93010224S   | SHOCK SPRING 35N/MM - 210MM    |  | 0.00 |
| 13 | 93010225S   | SHOCK SPRING 40N/MM - 210MM    |  | 1.00 |
| 13 | 93010226S   | SHOCK SPRING 45N/MM - 210MM    |  | 0.00 |
| 14 | 36120386    | Spring retainer 27x57x2        |  | 1.00 |
| 15 | 36120781S12 | MONOSHOCK LOWER PART CPL.      |  | 1.00 |
| 16 | 52000143    | STICKER WP WARNING 65X40       |  | 1.00 |
| 17 | 36120040    | Pistonring 33x35x8             |  | 1.00 |
| 18 | 50180217    | O-ring 27x1,5 Viton70 green IS |  | 1.00 |
| 98 | 50180751S1  | SHOCK ABSORBER FLUID 5 LT      |  | 1.00 |
| 99 | R12023      | REPAIR KIT                     |  | 1.00 |