



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|-------------|-------------------------------|-----------------|----------|
| 1 | 27007113144 | FUEL TANK CPL. | | 1.00 |
| 2 | 78105081010 | SCREW TORX M5X10 | | 3.00 |
| 3 | 76507108050 | Closure flange | | 1.00 |
| 4 | 78105081010 | SCREW TORX M5X10 | | 1.00 |
| 5 | 57013070100 | PVC-CLAMP 7,9 MM HEYCO 3355 | | 1.00 |
| 6 | 58207080100 | GAS-LEVEL SENSOR ADV. 2006 | | 1.00 |
| 7 | 0912050163 | AH collar screw DIN 912 M5x16 | | 2.00 |
| 8 | 27007028000 | RIGHT FUEL-TANK SUPPORT PLATE | | 1.00 |
| 9 | 27007027100 | Retaining bracket tank left | | 1.00 |
| 10 | 0025080166 | HH COLLAR SCREW M8X16 TX40 | | 6.00 |
| 11 | 27007053000 | CLAMP FOR SEAT LOCK LINKAGE | | 1.00 |

| | | | | |
|----|----------------|-------------------------------|------------|------|
| 12 | 27007008000 | TANK CAP | | 1.00 |
| 13 | 0738060181 | BHCS ISO 7380 M6X18 | | 2.00 |
| 14 | 76507050000 | SEAT LOCK | | 1.00 |
| 15 | 76507060000 | BEARING BUSHING UP | | 2.00 |
| 16 | 76507066000 | RUBB.BEAR.BOX 12x24x35 L=24,5 | | 2.00 |
| 17 | 0025080306S | HH COLLAR SCREW M8X30 TX40 | | 2.00 |
| 18 | 76507061000 | BEARING BUSHING DOWN | | 1.00 |
| 19 | 76507065100 | RUBBER BUSHING 11,7X24,7 L=26 | | 2.00 |
| 20 | 27007040000 | SEAT CPL. | | 1.00 |
| 21 | 27007040045 | SEAT RUBBER | | 4.00 |
| 22 | 2700804100028A | REAR SPOILER RIGHT | WITH DECAL | 1.00 |
| 23 | 2700804000028A | REAR SPOILER LEFT | WITH DECAL | 1.00 |
| 24 | 76506010100 | Splash protection | | 1.00 |
| 25 | 0025060166 | HH collar screw M6x16 TX30 | | 2.00 |
| 26 | 72210079000 | BUCKET | | 2.00 |
| 27 | 2700805400028A | SPOILER SET ENDURO 17 | WITH DECAL | 1.00 |
| 28 | 69008021160 | special screw M5x12 | | 4.00 |
| 29 | 69008021060 | special screw M5x17 | | 4.00 |
| 30 | 47106003160 | quick release rubber grommet | | 2.00 |
| 31 | 0770050030 | O-ring 50.00X3.00 VITON | | 1.00 |
| 32 | 27007097000 | Decalset seat 701 | | 1.00 |