



| Pos | Part Number  | Description                   | Additional Text | Quantity |
|-----|--------------|-------------------------------|-----------------|----------|
| 1   | 21011059000  | starter cable                 |                 | 1.00     |
| 2   | 0025060206   | HH collar screw M6x20 TX30    |                 | 4.00     |
| 3   | 76011053000  | BATTERY 12V 8AH               |                 | 1.00     |
| 4   | 21011054050  | Battery support               |                 | 1.00     |
| 5   | 21011055000  | Electric retainer             |                 | 1.00     |
| 6   | 21011097000  | mass cable frame-battery      |                 | 1.00     |
| 7   | 58411098100  | CONTACT WASHER M6 VSV-K6      |                 | 2.00     |
| 8   | 21011059050  | battery cable                 |                 | 1.00     |
| 9   | 014579050081 | Screw ISO 14579 M5x08-8.8-P3R |                 | 1.00     |
| 10  | 60011034100  | VOLTAGE REGULATOR             |                 | 1.00     |

|    |             |                              |  |      |
|----|-------------|------------------------------|--|------|
| 11 | 0024060256  | HH COLLAR SCREW M6X25 TX30   |  | 2.00 |
| 12 | 58411096100 | DIODE S3H-15 97              |  | 1.00 |
| 13 | 21011096000 | mass cable starter-frame     |  | 1.00 |
| 17 | 62111059060 | COVER POSITIVE POLE          |  | 1.00 |
| 18 | 0025060166  | HH collar screw M6x16 TX30   |  | 1.00 |
| 19 | 12011016000 | WASHER 6 X 12 X 3            |  | 1.00 |
| 21 | 0025060106  | HH collar screw M6x10 TX30   |  | 1.00 |
| 22 | 0025060126  | HH collar screw M6x12 TX30   |  | 2.00 |
| 23 | 69004060050 | Chain slider bushing         |  | 2.00 |
| 24 | 76211058000 | Starter relay                |  | 1.00 |
| 25 | 0912060083  | AH collar screw DIN 912 M6x8 |  | 2.00 |