



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|---------------|----------------------------|-----------------|----------|
| 1 | 28111175000 | Wiring Harness | | 1.00 |
| 2 | 28111060000 | Horn | | 1.00 |
| 3 | J900000801600 | Hexagon collar screw M8x16 | | 1.00 |
| 4 | J025060169 | HH COLLAR SCREW M6X16 SW8 | | 2.00 |
| 5 | 93541088000 | rollover sensor | | 1.00 |
| 6 | J125080006 | Washer M8 | | 1.00 |
| 7 | 90511030000 | indicator relay | | 1.00 |
| 9 | 75011088010 | FUSE 10A 07 | | 9.00 |
| 10 | 75011088015 | FUSE 15A 07 | | 3.00 |
| 11 | 75011088030 | FUSE 30A | | 2.00 |
| 12 | 90611057000 | relay (interlock) | | 5.00 |
| 13 | 93511084000 | PIGTAIL PH-3 FUEL PUMP | | 1.00 |
| 14 | 28111096000 | Transil unit | | 1.00 |
| 15 | 90211059000 | CABLE RELAY TO MOTOR | | 1.00 |
| 20 | J025060122 | Hex collar screw M6X12 | | 2.00 |
| 21 | J797060003 | TOOTHED WASHER M6 | | 2.00 |
| 22 | 28611075000 | Main wiring harness | | 1.00 |
| 23 | J025060303 | FLANGED BOLT M6X30 WS10 | | 2.00 |
| 24 | 28111097000 | CABLE EARTH | | 1.00 |

| | | | | |
|----|---------------|--------------------------------|--|------|
| 25 | 93038091000 | Pigteil oil pressure switch | | 1.00 |
| 26 | 93811099000 | wiring harness temperatur sens | | 1.00 |
| 27 | 28111034000 | Voltage regulator | | 1.00 |
| 29 | 93011058000 | Starter relais | | 1.00 |
| 30 | 93311058000 | Rubber damper starter relay | | 1.00 |
| 31 | 28111054000 | BRACKET MOUNT UNIT ELECTRICAL | | 1.00 |
| 32 | 28111054010 | Retaining cap, diagnostics con | | 1.00 |
| 33 | 93008020060 | Screw M6X1X9 | | 3.00 |
| 34 | 93007047033 | Seat support complete | | 2.00 |
| 35 | J900000803500 | bolt soket-m8x1.25xl35xcl8.8xb | | 2.00 |
| 99 | 93042033000 | Cable earth ABS | | 1.00 |