



| Pos | Part Number | Description | Additional Text | Quantity |
|-----|--------------|---------------------------|-----------------|----------|
| 1 | 96311075000 | main harness | | 1.00 |
| 2 | 90611057000 | relay (interlock) | | 5.00 |
| 3 | 93511088000 | Fuse 10a | | 7.00 |
| 3 | 90111088015 | Fuse 15A | | 5.00 |
| 3 | 90111088020 | Fuse 20A | | 2.00 |
| 3 | 90111088025 | FUSE 25A | | 2.00 |
| 3 | 90111088030 | Fuse 30A | | 1.00 |
| 4 | 96311059000 | Starter cable | | 1.00 |
| 5 | 96311098000 | CABLE EARTH | | 1.00 |
| 6 | A61711076060 | CABLE UNIT CONNECTIVITY | | 1.00 |
| 7 | 96338091000 | cable switch pressure oil | | 1.00 |
| 8 | 96311097002 | Busbar plate | | 1.00 |

| | | | |
|----|---------------|---------------------------------|------|
| 9 | 96311007000 | CABLE PUMP FUEL | 1.00 |
| 10 | 96311081000 | Rear turn signal wiring harness | 1.00 |
| 11 | 96311097000 | CABLE EARTH | 1.00 |
| 16 | J900000801402 | Hex collar screw, M8x14 | 1.00 |
| 17 | 28111060000 | Horn | 1.00 |
| 18 | J025060307 | bolt-flanged-small black | 2.00 |
| 19 | 96311034000 | Regulator assembly | 1.00 |
| 20 | J900000601803 | Hex screw with collar M6x18 | 5.00 |
| 21 | J800000601000 | collar number plate mounting | 3.00 |
| 22 | J650001801400 | grommet | 3.00 |
| 23 | 95842090000 | SENSOR LEAN ANGLE | 1.00 |
| 24 | 28111096000 | Transil unit | 1.00 |
| 25 | J025060122 | Hex collar screw M6X12 | 2.00 |
| 26 | J797060003 | TOOTHED WASHER M6 | 3.00 |
| 27 | J797100006 | washer toothed internal | 1.00 |
| 28 | 93011058000 | Starter relais | 1.00 |
| 29 | 93811099000 | wiring harness temperatur sens | 1.00 |
| 30 | 93311058000 | Rubber damper starter relay | 1.00 |
| 31 | 96311041000 | socket charger USB | 1.00 |
| 32 | 96342091010 | 6-D sensor retaining bracket | 1.00 |
| 33 | 96311058010 | cap relay starter | 1.00 |
| 34 | 96314086000 | UNIT CONNECTIVITY | 1.00 |
| 35 | 95842092020 | cover sensor lean angle upper | 1.00 |
| 36 | A61711039000 | COVER CONNECTOR | 1.00 |
| 37 | 96311053010 | CAP BATTERY POSITIVE | 1.00 |