




| Pos | Part Number  | Description               | Additional Text | Quantity |
|-----|--------------|---------------------------|-----------------|----------|
| 1   | 96311075000  | main harness              |                 | 1.00     |
| 2   | 90611057000  | relay (interlock)         |                 | 5.00     |
| 3   | 93511088000  | Fuse 10a                  |                 | 7.00     |
| 3   | 90111088015  | Fuse 15A                  |                 | 5.00     |
| 3   | 90111088020  | Fuse 20A                  |                 | 2.00     |
| 3   | 90111088025  | FUSE 25A                  |                 | 2.00     |
| 3   | 90111088030  | Fuse 30A                  |                 | 1.00     |
| 4   | 96311059000  | Starter cable             |                 | 1.00     |
| 5   | 96311098000  | CABLE EARTH               |                 | 1.00     |
| 6   | A61711076060 | CABLE UNIT CONNECTIVITY   |                 | 1.00     |
| 7   | 96338091100  | CABLE SWITCH PRESSURE OIL |                 | 1.00     |
| 8   | 96311097002  | Busbar plate              |                 | 1.00     |

|    |               |                                 |  |      |
|----|---------------|---------------------------------|--|------|
| 9  | 96311007000   | CABLE PUMP FUEL                 |  | 1.00 |
| 10 | 96311081000   | Rear turn signal wiring harness |  | 1.00 |
| 11 | 96311097000   | CABLE EARTH                     |  | 1.00 |
| 16 | J900000801402 | Hex collar screw, M8x14         |  | 1.00 |
| 17 | 28111060000   | Horn                            |  | 1.00 |
| 18 | J025060307    | bolt-flanged-small black        |  | 2.00 |
| 19 | 96311034000   | Regulator assembly              |  | 1.00 |
| 20 | J900000601803 | Hex screw with collar M6x18     |  | 5.00 |
| 21 | J800000601000 | collar number plate mounting    |  | 3.00 |
| 22 | J650001801400 | grommet                         |  | 3.00 |
| 23 | 95842090000   | SENSOR LEAN ANGLE               |  | 1.00 |
| 24 | 28111096000   | Transil unit                    |  | 1.00 |
| 25 | J025060122    | Hex collar screw M6X12          |  | 2.00 |
| 26 | J797060003    | TOOTHED WASHER M6               |  | 3.00 |
| 27 | J797100006    | washer toothed internal         |  | 1.00 |
| 28 | 93011058000   | Starter relais                  |  | 1.00 |
| 29 | 93811099000   | wiring harness temperatur sens  |  | 1.00 |
| 30 | 93311058000   | Rubber damper starter relay     |  | 1.00 |
| 31 | 96311041000   | socket charger USB              |  | 1.00 |
| 32 | 96342091010   | 6-D sensor retaining bracket    |  | 1.00 |
| 33 | 96311058010   | cap relay starter               |  | 1.00 |
| 34 | 96314086000   | UNIT CONNECTIVITY               |  | 1.00 |
| 35 | 95842092020   | cover sensor lean angle upper   |  | 1.00 |
| 36 | A61711039000  | COVER CONNECTOR                 |  | 1.00 |
| 37 | 96311053010   | CAP BATTERY POSITIVE            |  | 1.00 |